

INSTRUCTION MANUAL

MigaMonitor



MIGATRONIC

MigaMonitor

Instruction manual

Introduction

MigaMonitor is a software program, which makes it possible to store welding data and present those on a computer. The program is designed for Migatronik welding equipment and can operate together with FLEX 4000/5000 and SIGMA 300/400/500. The system exchanges data via the Migatronik CAN-bus system and takes advantage of the very precise measuring system in digitally controlled welding equipment. The MigaMonitor kit consists of the following items:

18600101 PC-kit MigaMonitor

- CD with the MigaMonitor software and drivers.
- 50113464 Instruction manual for MigaMonitor
- Interface cable

The program can be installed in either a Laptop or on a Desktop PC. The PC shall be equipped with at CAN-bus interface card as specified below.

System requirements:

The Migamonitor software can operate on Windows 2000 or Windows XP.

The PC used for connection to the welding equipment shall be equipped with a CAN-bus card from the below mentioned supplier. CAN-bus card from other suppliers will not work together with the program.

Specification for the CAN-bus interface card:

	Manufactur	Item no	Description
Laptop:	National Instruments,	777499-01,	PCMCIA-CAN, 1-PORT
Disktop:	National Instruments,	777357-01,	PCI-CAN, 1-PORT, 9-PIN DSUB
Website:	www.ni.com		


Installation:

Installation of the CAN-bus card must not be carried through before the software has been installed on the PC. The software, which is supplied with the CAN-bus card from National Instruments, shall not be used. All necessary software for the MigaMonitor system can be found on the MigaMonitor CD.

Insert the MigaMonitor CD into the PC and start the installation with the command: setup. Follow the instructions on the screen. Switch of the PC when the installation of the software is completed and mount the CAN-bus card into the PC following the instruction from National instruments.


Configuration of the CAN-bus card.

Start the program "Measurement & Automation" from the Windows "Start" bottom and the "Programs" menu.




From the start screen of "Measurement & Automation", click on "Devices and Interfaces" and PCI-CAN in "Configuration".

Right-click on CAN0 and select "Properties"




Select the correct Baud Rate according to the current welding equipment:


- Flex 4000 : 125 kbaud
- Flex 5000 : 125 kbaud
- Sigma 300 : 250 kbaud
- Sigma 400 : 250 kbaud
- Sigma 500 : 250 kbaud



CAN card test:
Right-click on "PCI-CAN" and click on "self-test"



The following screen will be displayed after the CAN-card has passed the test




Now the installation procedure of the hardware is completed.

Configuration of the MigaMonitor software

When the MigaMonitor is started for the first time a special configuration menu will be displayed. Fill in the registration name (company name) and registration code (Key) supplied together with the software.

Select equipment type and fill in "Connection to power source". The PC does not need a CAN-bus card if it is used only for analysis of welding data and print out. Finalise by pushing the registration bottom.




If a Key has not been supplied together with the program you can continue in evaluation mode. In this mode the number of records in each welding job are limited to 20 and printout function are blocked.

A valid code can be obtained by contacting your Migatronik dealer.

The program must be restarted before it is ready for use.

Use of the program

At the beginning of the program, the following picture will be displayed on the screen:




Create Job

It's necessary to create a welding job before you can store welding data on the harddisk on your PC. Push <F3> and follow the instruction on the screen. Pushing Save/<F8> saves when the data are filed in the job. It's also possible to reload a job and use this as a template for creating a new job.

Change of default directory.

By this function it is possible to change the default directory used for storing welding data.


- Go to the next directory.
- Go to rod directory
- Create a new directory
- Select this directory as default.



Select Job

In this function, the welding job, in which the records are saved, is selected.
Push the bottom "Select Job/<F4>" on the main screen.

- Current directory
- The current job specification
- Alarm settings in current welding job
- Step up and down.
- Select the welding job
- Cancel – return without any changes
- Change current directory and create new directories.



Alarm settings

Alarm settings are associated to each welding job. Alarm limits for maximum and minimum value of welding Current, Voltage and Wire feed speed can be adjusted.


Eg: If the expected welding current is 235 A the minimum limit can be adjusted to 200 A and the maximum limit can be adjusted to 270 A and the bottom is set to "ON".

Result: On all records in this job, there will be markings if the limits are exceeded. The number of samples with exceeded limits will be shown.

Alarm delay

During welding start the alarm can be disabled. Alarm delay is the time from start of welding to the time where the alarm is enabled.

Travel speed and **Process factor** is used for calculation of the heat input, shown on the graph.



Recording of welding data

The program is ready for storage of welding data when the welding job is selected and data are stored on the harddisk. The following data is shown on the screen during recording.

Current record number

Next record number

Number of alarms during last record

Current alarm

Voltage alarm

Wire feed alarm

Alarm marking on graph
(Alarms during alarm delay is not counted)

Green indicates that communication to the power source is working as intended


Voltage on torch

Arc established

Arc established or post timer running

Activate calculated average value during last welding record

Reading of wire speed, welding current and welding voltage.
Colours are equal to the graphs.



View Graph

Push on View Graph/F6 from the main screen activates this screen which is used for navigation of the records.

Select the graph, <5> and <F6>.

Select the directory

Select the job

<PdUp> and <PdDn>

View Graph

Pushing <F3> and <F4> recalls the highlighted graph. The same bottoms are used to return to this screen from the graphs, <F3> is used for stepping return and <F4> for stepping forward.

Job data


Alarm settings

Options

Record time scale: choose between Auto or exact settings.

No of pages: No of pages used for the current graph.

Graph No/page: no of graphs on each page.



Graph

Printing graph: push Ctrl+P or select Print window on menu.

Return, push <Esc>, <F3> or <F4>.

Select page no


Move cursor <F5> and <F6>

Cursor column

Average column

Setting of supposed travel speed
(Only this value can be changed).

Record information



Set-up screen

Push <Ctrl> + <F1> activate the set-up screen.

This function can be protected by a set-up password. By default there is no password protection.

Control mode

PC equipped with a CAN card or not.

Equipment type

If SIGMA 300/400/500 is selected the baud-rate on the CAN-card shall be changed. This is done in the measurement and automation program as shown on page 3.

The screenshot shows a software configuration window titled "MigaMonitor". It contains several input fields and a dropdown menu. The "Path" field is set to "C:\MigaMonitor\Log". The "User" field contains "ABC Industries Ltd". The "Key" field contains "2H4Q60LQ90KCUNAJ". The "Control Mode" dropdown is set to "Computer not equipped with CAN-card (off-line)". The "Equipment type" dropdown is set to "Flex4000". To the right of this dropdown, there is a note: "Remember to set the Baud-rate in the hardware setup in National Instrument - Measurement & Automation Explore Flex: 125k Sigma: 250k". The "Setup Password" field contains "US2Q4C6R". At the bottom, there is a message: "Changes in settings will take place after restart of the program." and two buttons: "Cancel Esc" and "Enter".

MIGATRONIC

Bundesrepublik Deutschland:

MIGATRONIC SCHWEISSMASCHINEN GmbH
Sandusweg 12, D-35435 Wettenberg
Telefon: (+49) 641 982840
Telefax: (+49) 641 9828450

Czech Republic:

MIGATRONIC CZECH REPUBLIC a.s.
Tolstého 451, 415 03 Teplice, Czech Republic
Telefon: (+42) 0411 135 600
Telefax: (+42) 0417 533 072

Danmark:

MIGATRONIC AUTOMATION A/S
Knosgårdvej 112, 9440 Aabybro
Telefon: (+45) 96 96 27 00
Telefax: (+45) 96 96 27 01

Danmark:

SVEJSEMASKINEFABRIKKEN MIGATRONIC
Aggersundvej 33, 9690 Fjerritslev
Telefon: (+45) 96 500 600
Telefax: (+45) 96 500 601

Finland:

MIGATRONIC OY
PL105, 04301 Tuusula, Finland
Tel. (+358) 0102 176500

France:

MIGATRONIC EQUIPEMENT DE SOUDURE S.A.R.L.
Parc Avenir II, 313 Rue Marcel Merieux, F-69530 Brignais
Tél: (+33) 478 50 6511
Télécopie: (+33) 478 50 1164

Hungary:

MIGATRONIC KFT
Szent Miklos u. 17/a, H-6000 Kecskemét
Tel./fax: +36/76/505-969; 481-412; 493-243

India:

Migatron India Private Ltd.
22, Sowri Street, Alandur, 600 016 Chennai, India
Tel.: (0091 44) 22300074
Telefax: (0091 44) 22300064

Italia:

MIGATRONIC s.r.l.
Via dei Quadri 40, 20871 Vimercate (MB) Italy
Tel.: (+39) 039 92 78 093
Telefax: (+39) 039 92 78 094

Nederland:

MIGATRONIC NEDERLAND B.V.
Hallenweg 34, NL-5683 CT Best
Tel.: (+31) 499 37 50 00
Telefax: (+31) 499 37 57 95

Norge:

MIGATRONIC NORGE A/S
Industriveien 1, N-3300 Hokksund
Tel. (+47) 32 25 69 00
Telefax: (+47) 32 25 69 01

Sverige:

MIGATRONIC SVETSMASKINER AB
Nåås Fabriker, Box 5015, S-448 50 TOLLERED
Tel. (+46) 31 44 00 45
Telefax: (+46) 31 44 00 48

United Kingdom:

MIGATRONIC WELDING EQUIPMENT LTD.
21, Jubilee Drive, Belton Park, Loughborough
GB-Leicestershire LE11 5XS
Tel. (+44) 15 09 26 74 99
Fax: (+44) 15 09 23 19 59

Homepage: www.migatron.com

