

AUTOMIG PULSE PROGRAM TABLE

Material	Diameter	Gas specification		Polarity	Program number	Item number	PROGRAM PACKAGE	PROCESS		
							Standard 10681030	DC	Pulse	
Manual MIG/MAG		CO ₂	100	+	002	10680002	x	x		
Manual MIG/MAG		ArCO ₂	82/18	+	003	10680003	x	x		
Fe SG2 ER70S6	ø 0.6 mm	CO ₂	100	+	106	10680106	x	x		
		ArCO ₂	82/18	+	116	10680116	x	x	x	
	ø 0.8 mm	CO ₂	100	+	101	10680101	x	x		
		ArCO ₂	82/18	+	111	10680111	x	x	x	
	ø 0.9 mm	CO ₂	100	+	109	10680109	x	x	x	
		ArCO ₂	82/18	+	119	10680119	x	x	x	
	ø 1.0 mm	CO ₂	100	+	102	10680102	x	x		
		ArCO ₂	82/18	+	112	10680112	x	x	x	
	ER 316 LSi	ø 0.8 mm	ArCO ₂	98/2	+	201	10680201	x	x	x
		ø 0.9 mm	ArCO ₂	98/2	+	209	10680209	x	x	x
ø 1.0 mm		ArCO ₂	98/2	+	202	10680202	x	x	x	
AlMg5 ER5356	ø 0.8 mm	Ar	100	+	311	10680311	x	x		
		Ar	100	+	319	10680319	x	x	x	
	ø 0.9 mm	Ar	100	+	312	10680312	x	x	x	
		ArHe	70/30	+	316	10680316	x	x	x	
	ø 1.0 mm	ArHe	50/50	+	332	10680332	x	x	x	
		Ar	100	+	313	10680313	x	x	x	
	ø 1.2 mm	ArHe	70/30	+	317	10680317	x	x	x	
		ArHe	50/50	+	333	10680333	x	x	x	
	AlMg3Mn ER5554	ø 0.9 mm	Ar	100	+	369	10680369	x	x	
		ø 0.9 mm	Ar	100	+	359	10680359	x	x	
AlSi5 ER4043	ø 1.0 mm	Ar	100	+	352	10680352	x	x	x	
		ArHe	70/30	+	356	10680356	x	x	x	
	ø 1.2 mm	Ar	100	+	353	10680353	x	x	x	
		ArHe	70/30	+	357	10680357	x	x	x	
AlSi12 ER4047	ø 1.0mm	Ar	100	+	372	10680372	x	x	x	
	ø 1.2 mm	Ar	100	+	373	10680373	x	x	x	
AlSi10Cu4 ER4145	ø 1.2 mm	Ar	100	+	393	10680393	x	x		
CuAl8 Brazing	ø 0.8 mm	Ar	100	+	501	10680501	x	x	x	
	ø 0.9 mm	Ar	100	+	509	10680509	x	x		
	ø 1.0 mm	Ar	100	+	502	10680502	x	x	x	
CuAl8 Welding	ø 0.8 mm	Ar	100	+	571	10680571	x		x	
	ø 1.0 mm	Ar	100	+	572	10680572	x		x	
CuSi3 Brazing	ø 0.8 mm	Ar	100	+	561	10680561	x	x	x	
	ø 0.9 mm	Ar	100	+	569	10680569	x	x	x	
	ø 1.0 mm	Ar	100	+	562	10680562	x	x	x	

Note: the number of available programs may vary from your machine, as it depends on date of purchase. Please contact your Migatronc dealer for purchase of new licenses.

AUTOMIG PULSE PROGRAM TABLE

Material	Diameter	Gas specification		Polarity	Program number	Item number	PROGRAM PACKAGE	PROCESS		
							Standard 10681030	DC	Pulse	
Manual MIG/MAG		CO ₂	100	+	002	10680002	x	x		
Manual MIG/MAG		ArCO ₂	82/18	+	003	10680003	x	x		
Fe SG2 ER70S6	ø 0.6 mm	CO ₂	100	+	106	10680106	x	x		
		ArCO ₂	82/18	+	116	10680116	x	x	x	
	ø 0.8 mm	CO ₂	100	+	101	10680101	x	x		
		ArCO ₂	82/18	+	111	10680111	x	x	x	
	ø 0.9 mm	CO ₂	100	+	109	10680109	x	x	x	
		ArCO ₂	82/18	+	119	10680119	x	x	x	
	ø 1.0 mm	CO ₂	100	+	102	10680102	x	x		
		ArCO ₂	82/18	+	112	10680112	x	x	x	
	ER 316 LSi	ø 0.8 mm	ArCO ₂	98/2	+	201	10680201	x	x	x
		ø 0.9 mm	ArCO ₂	98/2	+	209	10680209	x	x	x
ø 1.0 mm		ArCO ₂	98/2	+	202	10680202	x	x	x	
AlMg5 ER5356	ø 0.8 mm	Ar	100	+	311	10680311	x	x		
		Ar	100	+	319	10680319	x	x	x	
	ø 0.9 mm	Ar	100	+	312	10680312	x	x	x	
		ArHe	70/30	+	316	10680316	x	x	x	
	ø 1.0 mm	ArHe	50/50	+	332	10680332	x	x	x	
		Ar	100	+	313	10680313	x	x	x	
	ø 1.2 mm	ArHe	70/30	+	317	10680317	x	x	x	
		ArHe	50/50	+	333	10680333	x	x	x	
	AlMg3Mn ER5554	ø 0.9 mm	Ar	100	+	369	10680369	x	x	
		ø 0.9 mm	Ar	100	+	359	10680359	x	x	
AlSi5 ER4043	ø 1.0 mm	Ar	100	+	352	10680352	x	x	x	
		ArHe	70/30	+	356	10680356	x	x	x	
	ø 1.2 mm	Ar	100	+	353	10680353	x	x	x	
		ArHe	70/30	+	357	10680357	x	x	x	
AlSi12 ER4047	ø 1.0mm	Ar	100	+	372	10680372	x	x	x	
	ø 1.2 mm	Ar	100	+	373	10680373	x	x	x	
AlSi10Cu4 ER4145	ø 1.2 mm	Ar	100	+	393	10680393	x	x		
CuAl8 Brazing	ø 0.8 mm	Ar	100	+	501	10680501	x	x	x	
	ø 0.9 mm	Ar	100	+	509	10680509	x	x		
	ø 1.0 mm	Ar	100	+	502	10680502	x	x	x	
CuAl8 Welding	ø 0.8 mm	Ar	100	+	571	10680571	x		x	
	ø 1.0 mm	Ar	100	+	572	10680572	x		x	
CuSi3 Brazing	ø 0.8 mm	Ar	100	+	561	10680561	x	x	x	
	ø 0.9 mm	Ar	100	+	569	10680569	x	x	x	
	ø 1.0 mm	Ar	100	+	562	10680562	x	x	x	

Note: the number of available programs may vary from your machine, as it depends on date of purchase. Please contact your Migatronc dealer for purchase of new licenses.